

## FRAWG - Recommendations Approved 08/30/2017

Unit Name	Resource Requested	Scope	Priority	Fund	Comment
Child Development	Tables for CDC-132 In order to support a more effective and equitable instructional experience for our students, college classrooms CDC-114 and CDC-132 need to be modified. In particular, additional white boards are needed for the side walls in both classrooms, as the projection screen covers the front white boards. These white boards would be utilized by both students and faculty for demonstrations and group reporting. The tables in CDC-132 need to be replaced with smaller tables in order to allow for movement between aisles (this is a pedagogical issue in that faculty are impeded in their ability to circulate around the room during class activities and lecture; it also impacts accessibility for individuals with disabilities, and finally, poses an emergency evacuation concern). A few left-handed desks that match the size and appearance of the other desks in CDC-114 are also needed (the classroom is too small to use the campus desks that have been brought in previously for this purpose). The content of many CD courses includes learning environments, yet our learning environments for adults does not provide a good model. The CPU on the smart cart in CDC-114 needs to be replaced as the DVD drive is not functional; this impedes access to closed-captioning.	Small	1		Need to determine scope so a cost can be determine. Study in 2017/18 for possible funding later in the year.
Child Development	Snake guard for outdoor playground to promote safety of outdoor areas. As part of the current trends and practices in the field of Child Development, the CDC will become a certified outdoor classroom environment. This allows our students to gain valuable experience working within and planning for this approach/philosophy. Additionally, this could serve to attract more families to enroll in the CDC program.	Small	1	1,000.00	
Counseling	Additional signage directing students to a centralized check-in area for the center atrium area of Fountain Hall needs to be drastically improved. There is no clear direction of where to go first as students enter the building from 4 different points of entry. Students are continuously redirected numerous times resulting in high levels of frustration and often resulting in late arrival to appointment times with Counselors.	Small	1	5,000.00	
Kinesiology/ICA	Replace existing fencing behind home plate netting (compliance rules change)	Large	1	125,000.00	Determine if this is a requirement before funding. Funds from local funds.
EATM	Fence along front road from front gate to zoo 2 needs to be replaced. Metal post are stable, but the two horizontal bars between each post frequently are pulled off by children visiting the zoo. Current facilities need to be maintained while pursuit of EATM Site Specific Facility Master Plan is in progress.	Small	1		Need to determine scope so a cost can be determine. Study in 2017/18 for possible funding later in the year.

## FRAWG - Recommendations Approved 08/30/2017

Unit Name	Resource Requested	Scope	Priority	Fund	Comment
Chemistry	Cabinetry with swinging doors, similar to what is installed now, needs to be expanded in order to store more chemicals and glassware. Particular focus is on safety and chemical storage.	Intermediate	1	50,000.00	
Performing Arts Ctr	Replacement of the Scene Shop floor	Intermediate	1	Forward to PAWG for Prioritization	
Art	Renovation of AA court yard area. The cement in the AA court yard is already slated to be replaced for multiple reasons, including safety. This is a space for students to congregate and mingle. Its an opportunity to create a synergistic space for the students. Remove existing benches and add a few (three or four) metal tables and chairs would work well.	Intermediate	1	30,000	
Kinesiology/ICA	Update Softball Dugouts Keep facilities updated and safe; meet compliance regulations	Intermediate	1	50,000.00	
Custodial Svcs	Supervisor Office Relocate supervisor office from Warehouse to office Bldg. Current office is inside the back of the warehouse in a make shift room.		In Process		

## FRAWG - Recommendations Approved 08/30/2017

Unit Name	Resource Requested	Scope	Priority	Fund	Comment
Dance	<p>Ventilation system in Dance Studio (PA-107) is inadequate for the level of physical activity in this room. This has been in our program plan since 2013. Adjusting with the air conditioning has proven to be ineffective as the temperature varies greatly through the course of the day and depending on the number of occupants at a given time.</p> <p>We have modified this request to be for ceiling fans to be installed that would move the air and promote healthy movement of the air as needed in addition to the central air system.</p>		In Process		
Political Science	Paint/repair bathrooms in HSS.		In Process		
Library	<p>Proposed safety enhancements:</p> <ul style="list-style-type: none"> <li>- Install panic buttons at both the reference desk and circulation desk.</li> </ul>	Small	In process		