	COMMITTEE MEMBER VOTING   1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 TOTA														٦				FACILITY REQUEST								
CATEGORY	1	2	3 4	1 5	5 6	7	8	9 10	) 11	1 12	2 13	14	<b>15</b> :	16 1	7 ТОТА	LS <mark>RA</mark>	<mark>ANK</mark>	ID	Unit Name	OppName	Opportunity	Resource Name	Resource Description				
MAJOR	1	.9 1	18	2 1	9	20	20	19	9 15	5 8				3 1	9 162		1	2	Program Plan - America's Teaching Zoo	Regulatory Agency Requirements	Continue to successfully meet zoo and wild/exotic animal regulatory agency requirements.	refurbish/replace aged and deteriroating enclosures	Concrete floors are cracked and deteriorating in carnivore and show areas. Mew infrastructure deteroirated.				
MAJOR	1	.2 2	20 !	5 1	8	9	18	16	5 18	8 19	5			1 1	6 148		2	3	Program Plan - Health Education	Instructional area(s) improvements	Improvements that assist instructors to aid student retention and success	HED 5 classes need space for Practical application	G-116 could be changed to meet needs for practical application and lecture. This room would need folding desks, updating smart classroom technology, improving ventilation and storage cabinets.				
MAJOR	1	.6 1	15	7 1	6	8	16	18	3 3	9				20 1	5 143		3	5	Program Plan - Kinesiology	Instructional area(s) improvements	Gym Renovation/classroom improvements	Classroom G-116 Storage for equipment	Built in cabinets for equipment storage				
MAJOR	2	0	4 19	1 2	0	7	19	3	13	3 7				2 2	<b>0</b> 134		4	1	Program Plan - America's Teaching Zoo	Modernize ATZ	Formulate a facilities plan to modernize ATZ	Hire architect to assist with formulating a master facilities plan	Faculty/staff discussions in progress to gain consistency on what should be done				
MAJOR	1	.4 :	L4 8	3 1	5	18	15	12	2 4	10	)			5 1	7 132		5	6	Program Plan - Kinesiology	Instructional area(s) improvements	Gym Renovation/classroom improvements	Classroom G-116 update ventilation and air conditioning	Room lacks adequate ventilation, air conditioning is inadequate				
MAJOR		<b>B</b> 1	111	0 1	2	15	13	11	6	20	,			6 1	<b>B</b> 130		6	8	Program Plan - Kinesiology	Instructional area(s) improvements	Gym Renovation/classroom improvements	classroom G-202- Construct sound proof wall between deck and gym floor	Construct sound proof wall between deck and gym floor- so area can be used as a teaching area				
MAJOR	1	.3 1	101	2 9	Ð	10	11	20	) 8	12	2			19 5	129		7	10	Program Plan - Kinesiology	Instructional area(s) improvements	Gym Renovation/classroom improvements	Classroom G-202 Storage for equipment	Construct locking storage cabinets for aerobic equipment				
MAJOR			9 1			14				14				17 8			8	11	Program Plan - Kinesiology	Instructional area(s) improvements	Gym Renovation/classroom improvements	Expand/Update G-127 -weight/ Power lifting classroom	Expand space to accommodate 12 Power rack and platform areas, dumbbell weight area with a 500 sq. ft. free exercise area, improve ventilation with air conditioning.				
MAJOR		6	7 1	6 5	5	13	7	15	5 12	2 16	5			15 1	<b>1</b> 123		9	14	Program Plan - Kinesiology	Instructional area(s) improvements	Gym Renovation/classroom improvements	Women's Locker room	Shower room face lift and a workable locker room with Athletic team lockers				
MAJOR	1	.5 1	L6 (	5 1	7	19	17	5	2	19	9			4 1	. 121	1	10	4	Program Plan - Kinesiology	Instructional area(s) improvements	Gym Renovation/classroom improvements	Athletic Training Room	Athletic Training area that meets current HIPPA laws. Room approx. 2500 sq. ft. area on ground level with large office for staff, Privacy office for exams, equal access to both locker room areas, access to athletic events areas and emergency vehicles, h				
MAJOR		7 1	12 1	1 1		17								7 1	0 119	1	11	9	Program Plan - Kinesiology	Instructional area(s) improvements	Gym Renovation/classroom improvements	Classroom G-202- develop ventilation for room	Develop ventilation for room with wall mounted fans or develop air conditioning for area				
MAJOR			6 1			12		14						14 3			12	13	Program Plan - Kinesiology	Instructional area(s) improvements	Gym Renovation/classroom improvements	Men's Locker Room	Showroom face lift, develop workable locker room with area for athletic team lockers, develop permanent walls for privacy entry/exits				
MAJOR			8 1			11	9			0 18				18 6			13	12	Program Plan - Kinesiology	Instructional area(s) improvements	Gym Renovation/classroom improvements	Gym Foyer	Update the gymnasium foyer areas. Remove old trophy cases and replace with more modern and attractive common areas.				
MAJOR			L3 9			16				11				9 2			14	7	Program Plan - Kinesiology	Instructional area(s) improvements	Gym Renovation/classroom improvements	Classroom G-202- Construct flooring for aerobic movement classes	Construct flooring for aerobic movement classes; area would be large enough to handle a normal size aerobic class				

	_	COMMITTEE MEMBER VOTING   2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 TOTALS RANK ID Unit I																			FACILITY REQUEST					
								IEE																		
CATEGORY	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	ΤΟΤΑΙ	S R	RANK	ID	2	Unit Name	OppName	Opportunity	Resource Name
MAJOR		18	17	1	4		5	5		13	20	5				10	9	107		15	15		ogram Plan - cilities Svcs	Improve FM&O Offices	Create a safer, more efficient working environment	Funds for Renovation Project
MAJOR		10	4	20	0 1		4	3		4	17	4				11	13	91		16	18	Kir	ogram Plan - nesiology	Stadium Changing Facility	Build Changing Facility	Stadium changing facility
MAJOR		2	5	17	7 3		6	6		9	19	3				13	7	90		17	16	Nu	ogram Plan - ırsing	Increase retention rates to the 80% goal	Retention rate (on-schedule completers) for Fall 2010 - Spring 2011 was 59% which decreased from 78% in Fall 2009 - Spring 2010 which did not meet the program goal of 80%. The rationale is that the end of the wait list contains the weaker students because	HSC Bridge to Lot E
MAJOR		17	1	3	2		3	4		6	14	6				12	12	80		18	17	Во	ogram Plan - okstore	Operational Efficiency	Improve technology and efficiencies to improve bookstore operations.	Remodel: Lights, Ceiling
MAJOR		1	3		3 10		2				16						4			19	20	Pro	ogram Plan - Art	Facilities Planning	Completion of Arts Complex in the AA building. All Art Studio classes will be moved to the AA building. See attached Facilities document.	AA Patio Shade Structures
MAJOR		3	2	19	9 11	L	1	1		1	1	2				8	14	63		20	19	AC	ogram Plan - CESS	Tutoring Area	The size of the tutoring area has increased, but because LMC 137 is still an open area, the noise from the tutoring area is distracting to the students taking exams or attempting to communicate with a staff member to make an appointment for assistance.	Wall in LMC 138
INTERMEDIATE		8	10	) 5	10		9	9		10	10	8				1	7	87		1	2	Da	ogram Plan - Ince	Dance Studio Maintenance	Implement a sustainable system to ensure a clean and healthy floor in PA 107 such as monthly deep cleanings with faculty cleaning as needed in-between.	Ventilation system
INTERMEDIATE		9	8	1	8		10	10		9	9	9				2	4	79		2	1		ogram Plan - Ince	Dance Studio Maintenance	Implement a sustainable system to ensure a clean and healthy floor in PA 107 such as monthly deep cleanings with faculty cleaning as needed in-between.	Dance Floor for PA 107

Resource Description
Create a safer, more efficient working environment for FM&O Offices
A 3,000-4,000 square foot facility with matching and identical men's and women's locker, meeting and shower areas. Included should be a separate, but attached to both locker rooms, area for a Training Room.
Work with other disciplines to support the building of a bridge between HSC and Parking Lot E for the safety of students that are required to cross the street otherwise.
Could be two separate requests: Lights: The back office uses exposed fluroescent light bulbs, which makes them out of compliance with OSHA. Consequently, they need to re-do the lighting. Ceiling: During the remodel we were unable to corrected the electrical wiring problems and the bookstore will need to be offline at this time and remove the asbestos. Not funded with general funding.
Move sculpting classes outside courtyard into shaded space; may display social area for students.
If issue is sound, we may be able to find other solutions. Possible suggestions would be to reserve LMC conference room or other classroom.
Ventilation system in Dance Studio (PA-107) is inadequate and needs to be improved
Marley floor replacement

	_				0	OMI	міт	TFF	MEM	RFR	VO	TING									2012-2013		FACILITY REQUEST
CATEGORY	1	2	3	4	5									15	16	17	TOTALS	RANK	ID	Unit Name	OppName	Opportunity	Resource Name
INTERMEDIATE	-	10					8				2 10		14	15	6	6	77	3		Program Plan -	Modernize ATZ	Formulate a facilities plan to modernize ATZ	Install additional outdoor lighting around zoo
INTERMEDIATE		4					7	6	7		, 7				10		66	4	5	Program Plan -	Facility Upkeep, Upgrades, and Maintenace	Various areas of the PAC and the surrounding area of campus are in need of upgrades, additions, and just general maintenance.	Dance Studio floor replacement
INTERMEDIATE		7	7	8	5		4	3	8	3 4	1 2				4	10	62	5	6	Program Plan - America's Teaching Zoo	Modernize ATZ	Formulate a facilities plan to modernize ATZ	Zoo 1 building renovation
INTERMEDIATE		5	3	6	7		6	7	1	. 3	8 6				8	3	55	6	4	Program Plan - America's Teaching Zoo	Modernize ATZ	Formulate a facilities plan to modernize ATZ	Refurbish old capuchin monkey enclosur
INTERMEDIATE		6	4	7	4		5	4	3	5 5	5 1				7	9	55	7	7	Program Plan - America's Teaching Zoo	Modernize ATZ	Formulate a facilities plan to modernize ATZ	Zoo 2 building renovation
INTERMEDIATE		1	5	9	1		1	5		5 6	5 5				5	1	44	8	10	Program Plan - Photography	CTEA Equipment and Facilities	Improvement of CTEA component. Continuing need for latest photographic equipment and facilities. Planned purchases through Perkins grants will help to bolster CTEA offerings. Planned renovations to HSS 129 (photo Studio) with acquisition of HSS 114,115, a	Track Lighting
INTERMEDIATE		3	6	4	3		2	2	4	1 8	3 3				3	5	43	9	0	Program Plan - Film/TV Media	instructional	Improve the instructional environment	Re-Wire Studio
INTERMEDIATE		2		10			3	1	2						9	2	37	10	9	Program Plan - Music	environment Acoustics in M114and M109	Acoustics in M114and M109 are not optimal for ensemble rehearsals.	Replace existing carpets in M114 and M10 with wood and/or tiles.
MINOR		6	6	1	6		6	5	e	5 2	2 5				2	3	48	1	1	Program Plan - Astronomy/Physics/ Physical Science	AC Power to Lab Benches	The "Modern Physics Laboratory" (PS-207) could be utilized more efficiently while also addressing the safety issue of supplying AC power to the lab benches.	SAFETY: AC Outlets
MINOR		5	4	5	4		5	6	5		3 6				1	4	48	2	2	Program Plan - Astronomy/Physics/ Physical Science	Charles Temple Observatory	The Charles Temple Observatory facility is inadequate to serve current student demand; significant health and safety issues exist.	Portable Toilet
MINOR		1					4		1			T			4	6	40	3	3	Program Plan - Art	Facilities Planning	Completion of Arts Complex in the AA building. All Art Studio classes will be moved to the AA building. See attached Facilities document.	AA building display cases for 2-D and 3D student work (new)

	Resource Description
nd	Still needed for safety and visibility with camera's for after 5 when the zoo is closed
	Permanent dance floor in studio needs to be replaced. Marley grey or white at \$1,600 per roll x 9 rolls needed totaling \$14,400
	In progress. Bathrooms still need refurbishing.
ıres	Paint roofs, add concrete block bedroom between the 2 enclosures, change out guillotine door into service door.
	Need lockers for students, painting, replace water stained ceiling tiles, replace carpet with linoleum sheet (not tiles), divide the room with moveable particiations
	Track lighting in digital lab HSS 118 to help with viewing of computer monitors.
	Re-Wire Studio
109	
	Electrical sources for physics are on the outside walls and could trip on the electrical cords.
)	Secondary effect to AA renovation, they would like new display cases for the AA building; need new ones because the old ones are old

					CO	MN	ΛΙΤΤ	'EE ſ	MEN	<b>IBE</b>	r vo	DTIN	G									FACILITY REQUEST					
CATEGORY	1	2	3	4	5	6	7	8	<b>9</b>	10	11	12	.3 1	4 1	5 16	5 17	ΤΟΤΑΙ	LS <mark>R</mark>	ANK	ID	Unit Name	OppName	Opportunity	Resource Name	Resource Description		
MINOR		4	3	6	5		1	1		3	6	2			3	1	35		4	5	Program Plan -	Location of Supervisor Office	Relocate supervisor office from Warehouse to office Bldg. Current office is inside the back of the warehouse in a make shift room.	Supervisor Office	Funds to Relocate Supervisor Office to Office Building		
MINOR		3	2	2	2		3	3		4	1	1			6	5	32		5		Program Plan - America's Teaching Zoo	Modernize ATZ	Formulate a facilities plan to modernize ATZ	2 new 8' x 10' metal sheds	Replace rust sheds storing cleaning tools and other items		
MINOR		2	1	3	1		2	2		2	5	3			5	2	28		6	6	Program Plan - Theater Arts	Classroom	All THA classrooms need to have secure storage, internet connectivity and be smart classrooms.	locking storage	Locking Storage in PA-128 and 129 Security for Scenic/Costume/Lighting Design Classes		

Major Facility requests (higher dollar, longer timeframe)Intermediate Facility requests (medium dollar, medium timeframe)Minor Facility requests (low dollar, short timeframe)